

AUGUST 5-6, 2020 Briefings

Reverse Engineering the Tesla Battery Management System to Increase Power Available

By Patrick Kiley

an and the second second for still the second second






Patrick Kiley – Principal Security Consultant - Rapid7

- Member of the Penetration Testing team at Rapid7
- Performed research in Avionics security
- Internet connected transportation platforms
- Experience in hardware hacking, IoT, Autonomous
 Vehicles, and CAN bus







Topics


- Architecture of the Model S and Battery Management System(BMS)
- Performance and Ludicrous timeline
- Hardware changes
- Data stored in toolbox
- Firmware changes
- Shunt modification
- Upgrade process
- Failure and what I learned
- Next steps





Model S Architecture

- Central Information Display (CID): Nvidia Tegra based
- Gateway: a security component, stores vehicle configuration, sits between the various CAN buses and the CID
- Powertrain (PT) CAN bus, contains the BMS, Drive units, charging, thermal control and other powertrain related controllers
- PT CAN runs at 500 kBit/sec and is a standard vehicle CAN bus (differential signaling, 11 bit arb ids, etc)
- PT CAN supports UDS standard






BMS Overview


- TI TMS320C2809 Main microprocessor
- Altera CPLD Hardware backup for TMS320
- Current Shunt with STM8, measures current coming from the battery
- Precharge Resistor, prevents inrush current damage
- BMB boards on each battery pack, these include bleed resistors to balance packs


All the firmware changes are on the TMS320 Some settings are changed on the shunt, in addition it has a small physical modification

Full reversing of all the components is an ongoing project, so if you want to help, I am lacking in some of the skill areas










Ludicrous History

- P85D announced on Oct 10, 2014
- Ludicrous announced on July 17, 2015
- 10K for new buyers, 5K for existing P85D owners
- Upgrade involved new contactors and pyro fuse.
- Many performance battery packs would come standard with new components
- They were "ludicrous capable"
- All 100kWh performance battery packs are "ludicrous capable"
- Ludicrous capable means add "performanceaddon 1" to internal.dat on the gateway





I upgraded a donor vehicle





Pack Dropped






Fuse and Contactor Bay





Shunt and Contactor Close up





What about firmware?

- For this we need to dig into some python
- Tesla makes a diagnostic tool called toolbox, runs on windows, uses encrypted and compiled python modules
- The important files are contained as individual plugins with the .scramble extension
- All of the information needed to decrypt the scramble files are on a machine that is running toolbox
- Some of these scramble files include firmware as well as many other useful items
- Once decrypted, we can use Uncompyle6 to give us source code
- Tesla left all the source code comments in place. Thank you!

Name	Туре	Size
hci-2018.0.6-win32.scramble	SCRAMBLE File	548 KB
tbx_chademo-2018.0.1-win32.scramble	SCRAMBLE File	311 KB
tbx_coyote_cam-2018.0.1-win32.scramble	SCRAMBLE File	140,060 KB
tbx_dev-2018.0.5-win32.scramble	SCRAMBLE File	184 KB
tbx_driver_assist-2018.0.8-win32.scramble	SCRAMBLE File	142 KB
tbx_engineering-2018.0.1-win32.scramble	SCRAMBLE File	232 KB
tbx_fw_update_ext-2018.24.1-win32.scramble	SCRAMBLE File	458 KB
tbx_fw_update-2018.0.2-win32.scramble	SCRAMBLE File	19 KB
tbx_gen2_firmware-2018.0.1-win32.scramble	SCRAMBLE File	22,107 KB
tbx_gen2_meta-2018.0.1-win32.scramble	SCRAMBLE File	3,415 KB
tbx_gen2-2018.36.26-win32.scramble	SCRAMBLE File	2,780 KB
tbx_key_pairing-2018.0.4-win32.scramble	SCRAMBLE File	1,102 KB
tbx_meta_18_2_23-18.2.23-win32.scramble	SCRAMBLE File	13,573 KB
tbx_rest-2018.0.3-win32.scramble	SCRAMBLE File	1,205 KB
tbx_restraint-2018.0.2-win32.scramble	SCRAMBLE File	1,341 KB
tbx_security-2018.0.4-win32.scramble	SCRAMBLE File	102 KB
tbx_service-2018.33.4-win32.scramble	SCRAMBLE File	1,257 KB
tbx_steering-2018.0.1-win32.scramble	SCRAMBLE File	75 KB
tbx_suspension-2018.0.1-win32.scramble	SCRAMBLE File	58 KB
tbx_testing-2018.36.1-win32.scramble	SCRAMBLE File	43 KB
tbx_third_party-2018.0.2-win32.scramble	SCRAMBLE File	5,381 KB
tbx_uss-2018.0.1-win32.scramble	SCRAMBLE File	92 KB



Toolbox Uncompyled

- 1 # uncompyle6 version 3.3.2
- 2 # Python bytecode 2.7 (62211)
- 3 # [GCC 5.4.0 20160609]
- 4 # Embedded file name: build\bdist.win32\egg\vehicle\core\uds\data.py
- 5 # Compiled at: 2017-07-27 11:08:07
- 6 __author__ = 'Eric Hulser'
- 7 __email__ = 'ehulser@teslamotors.com'
- 8 __copyright__ = 'Copyright Tesla Motors Inc. 2013'
- 9 import logging

14

- 10 from xqt import QtCore
- 11 from .object import UdsObject
- 12 from . import errors
- 13 log = logging.getLogger(__name__)

```
15 class UdsData(UdsObject):
```



Helpful Comments

Compiled at: 2017-07-26 15:43:06

```
.....
```

```
Defines the a VehicleTest to change the performance addon config.
```

```
__authors__ = [
   'Otto Chiu']
   __author__ = (',').join(__authors__)
   __credits__ = []
   __copyright__ = 'Copyright Tesla Motors Inc. 2015'
from tbx_gen2.testing import Gen2VehicleTest
import logging
log = logging.getLogger(__name__)
```

class PerformanceAddonConfig(Gen2VehicleTest):

```
def exec_(self):
    """
    First verify that a vehicle can be configured in the desired config.
    For Standard mode, there is no checks; for Ludicrous mode, the vehicle
    needs to be AWD and has a battery pack config that supports 1500A+ current discharge.
    """"
```



Data Structures – Extract and Binwalk

uncompyle6 version 3.3.2

Python bytecode 2.7 (62211)

Decompiled from: Python 2.7.12 (default, Nov 12 2018, 14:36:49)

[GCC 5.4.0 20160609]

Embedded file name: build\bdist.win32\egg\tbx_gen2_firmware\resources\pyside_tbx_gen2_firmware_rc.py
Compiled at: 2018-01-23 14:15:28


from xqt import QtCore

def qInitResources():
 QtCore.qRegisterResourceData(1, qt_resource_struct, qt_resource_name, qt_resource_data)

def qCleanupResources():
 QtCore.qUnregisterResourceData(1, qt_resource_struct, qt_resource_name, qt_resource_data)

qInitResources()

okay decompiling /home/can/Desktop/tbmaster/Roaming/Tesla/plugins/service_alpha//tbx_gen2_firmware-2018.0.



Bootloader

We already know from the donor vehicle's config that it had a pack id of "57"

These are the files we need from the extracted firmware


Pack id 57 becomes pack id 70 after the changes

Changes HWID from 57 to 70

http://artifacts.teslamotors.com/jenkins-job/bootloaders/git/21c44cbe0713a1beaa105b00cf - name: 57 Gateway Application description: HWID 57 Gateway Application for Shunt Calibration filename: firmware/bms/withSecondaryBoot_UDSBoot_BMS_GATEWAY_APP_HWID-57.hex ludicrousable: True hwid: 57 calibrateShunt: True linkedPackageName: 57 Updater

– name: 57 Updater description: HWID 57 Updater File filename: firmware/bms/withSecondaryBoot_UDSBoot_BMS-R57-CSM_UPDATER_SVN-68454.hex flashBootUpdater: True linkedPackageName: 70 Bootloader ludicrousable: True

name: 70 Bootloader
 description: HWID 70 Bootloader
 filename: firmware/bms/withSecondaryBoot_UDSBoot_BMS-R70-CSM_SVN-71214.hex
 changeBootHWID: True
 module: UDS_FLASH_B00TL0ADER
 linkedPackageName: 70 Application



Firmware Upgrade

- All the instructions and files needed for the upgrade process were stored in Toolbox files
- DBC files to help understand signals on the PT CAN bus
- ODX files that defined how to calibrate the shunt, grant security access and upgrade the firmware
- Files that stored calibration data and firmware
- Text comments and text data structures that offered clues on the process

< Þ / 4_0	GW4_ModelS_ESP_2.0.pickle ×
1408/93	sg148
1408794	S'BMS_maxDischargeCurrent'
1408795	p224102
1408796	sg149
1408797	g176423
1408798	sg159
1408799	FØ
1408800	sg103
1408801	(dp224103



CAN and UDS

Sitting on top of the CAN network stack is a protocol called UDS, or "Unified Diagnostic Services", this protocol can be used to help technicians:

- Diagnose problems
- Read values from sensors
- Update firmware

CAN networks use a descriptor file called a DBC file

UDS networks can use a scripting file called ODX or GMD

Used commercial tool Vehicle Spy to assist in the research

ARBS 7E2 and 202 from BMS identify max current as a static value. 232 (BMS), 266 (DI) and 2E5 (DIS), identify max power in watts, which varies based on SOC, temp, and power recently used





DBC Turns this

	Count	Time (abs/rel)	Тх	Er	A Description	ArbId/He	Len	DataBytes	Network
Filter									
?	3298	10.000 ms	;		HS CAN \$102	102	8	00 00 32 A6 64 4C 08 00	HS CAN
?	330	100.006 ms	;		HS CAN \$202	202	8	80 9D 1E 98 00 00 00 00	HS CAN
?	330	100.004 ms	;		HS CAN \$212	212	5	40 04 70 FF 00	HS CAN
?	33	1.000002 s	;		HS CAN \$218	218	8	7D 00 FF 27 FF DF 7F 37	HS CAN
?	330	100.238 ms	;		HS CAN \$222	222	6	00 00 00 00 00 10	HS CAN
?	330	100.474 ms	;		HS CAN \$232	232	4	88 26 5E 07	HS CAN
?	33	1.000020 s	;		HS CAN \$242	242	8	00 00 00 00 00 00 00 00	HS CAN
?	65	648 µs	;		HS CAN \$246	246	5	DB 00 F5 03 49	HS CAN
?	330	99.986 ms	;		HS CAN \$248	248	7	28 29 00 2F 01 31 00	HS CAN
?	330	101.181 ms	;		HS CAN \$252	252	7	00 00 00 00 02 2B 00	HS CAN
?	330	101.417 ms	;		HS CAN \$262	262	8	00 00 00 00 00 00 00 00	HS CAN
?	330	101.655 ms	;		HS CAN \$272	272	8	00 E0 43 FB 00 00 00 00	HS CAN
?	825	40.006 ms	;		HS CAN \$2BF	2BF	8	FF 0F FC FF FF FF 9F 61	HS CAN
?	330	100.002 ms	;		HS CAN \$2C8	2C8	8	60 B0 03 FF 20 24 20 40	HS CAN
?	330	101.664 ms	;		HS CAN \$2D2	2D2	7	00 00 00 00 06 00 00	HS CAN
2	33	1.000022 s	;		HS CAN \$302	302	8	00 00 10 00 5F 67 40 00	HS CAN



Into This

		Count	Time (abs/rel)	Tx	Er	A Description	ArbId/He	Len	DataBytes	Network
Filte	r									
+	ř	43	1.000973 s			BMS_energyStatus	382	8	5C 00 00 00 00 00 A0 10	HS CAN
+ "	Ô	4326	10.000 ms	}		BMS_hvBusStatus	102	8	00 00 32 A6 64 4C 08 00	HS CAN
+	Ô	4	10.001053 s	ł		BMS_iSensorInfo	532	8	00 00 00 00 00 00 00 00	HS CAN
+ "	Ô	31	1.000975 s	1		BMS_info	5D2	8	0D 00 00 00 A3 2A A2 39	HS CAN
+	Ô	43	1.001201 s	ł		BMS_kwhCounter	3D2	8	17 6E 68 00 31 DB 61 00	HS CAN
+ "	Ô	4	10.001059 s	1		BMS_odometerSta	562	4	DC D4 45 02	HS CAN
-	Ô	432	100.003 ms	ł		BMS_powerAvailable	232	4	88 26 5E 07	HS CAN
 	*	BMS_maxReg	genPower			= 98.640 kW	[2688]			
 	*	BMS_maxDis	chargePower			= 18.860 kW	[75E]			
+	ð	432	100.003 ms	}		BMS_ptNm	402	2	00 00	HS CAN
+	Ô	4	10.001053 s	ł		BMS_serialNumber1	542	7	54 31 35 4C 30 31 31	HS CAN
+	Ô	4	10.001053 s	1		BMS_serialNumber2	552	6	39 37 31 39 00 00	HS CAN
+	· S	43	1.000973 s			BMS socStatus	302	8	00 00 00 00 E9 D0 10 00	HS CAN



ODX routines for shunt calibration

+ - 🖻 🛍 📂 🖬	প 🕻 Tree	🚀 List	Results
			🖕 Setup 🧐 Results 🔤 Signals
Name	Status	~	🗷 🏴 TESLA_BOOT : \$22 Read Data By Id
∃ 🨝 User Jobs (saved in vs3) ⊟ 🖧 HS CAN			TESLA_BOOT: Positive Response S
	Stopped		 Positive Response from TESLA_BOOT
SE Tester Present	Stopped		SHUNT HWID = 4
🖃 🐻 \$602 : BMS			CGI1 DATA = 38406
••• \$23: Read Memory By Addre)		_
\$23 Read Memory By Add	r Stopped	CAU1 DATA = 38406	
😑 🗝 \$27 : Security Access			SHUNT CPC = 12640
\$27 Security Access - Get	! Stopped		$-$ SHUNT_CRC = 12640
📃 \$27 Security Access - Key	Stopped		SERIAL_NUMBER = 2107536
🗄 👐 \$3E : Tester Present		READ RESULT = Write Success	
🗏 🔚 \$602: TESLA_BOOT			_
🖃 🐜 \$22: Read Data By Identifier			USDT PCI (\$22) : Consecutive Frame :



Shunt Modification

- Shunt also needed a hardware modification
- Single wire connecting the shunt to the CPLD
- If this wire remained connected after the firmware update then the BMS would generate an alert and refuse to close the contactors
- Discovered ran through the upgrade process on a bench version of the components
- Made a breakout board to monitor the signals from the shunt
- This also meant that the hardware and firmware both had to be updated before the car was driven





Upgrade Process

- Had access to garage and lift in Southern California
- Drove there to do upgrade, arrive with low SOC
- Drop pack, do hardware stuff
- Reinstall pack, carefully (image is from borescope)
- Flash BMS with special firmware for shunt modification
- Flash BMS to new packID
- Update internal.dat to add ludicrous and change packID
- Redeploy firmware due to changed battery packID
- Drive away and enjoy the ridiculous amount of torque?





Final Steps

- Using known techniques that I have used before, I tried to redeploy the firmware, also tried to upgrade since I had access to several versions
- The car failed using every method I tried
- Had to Tow the car from Rancho Cucamonga to Las
 Vegas so I could continue to work on it
- Cost me \$360 or 3.6 hundred dollars, not great, not terrible right?






Learned something cool


- Gateway uses a file called firmware.rc
- Gateway uses this as a validation check for the components
- Calculated during upgrade/redeploy
- When the BMS changed, so did its CRC
- Changed the CRC based on CAN and value from "signed metadata map.tsv"
- Final CRC line is a JAMCRC based on overall file
- Car woke up, errors cleared and car could be driven
- Eventually figured out the reason for the earlier failure

< >	firmware.rc •
1	fileFormatVersion 1
2	platformType 1
3	platformVersion develop/2018.14.2-6-a88808ee6a
4	gtw 9acc071b
5	bms a0637e09
6	bmscpld 93.0.0
7	(removed for clarity)
8	dhrp 3.11.0
9	dhfp 3.11.0
10	dhrd 3.11.0
11	dhfd 3.11.0
12	fileCrc 271d96ad
13	




Power Before and After Upgrade

Before Upgrade 1300 Amps	PYO A 2:46.994872 BMS_1HzDebug_Id BMS_DRIVE_ctrWotCounter BMS_DRIVE_ctrWotCurrentLimit BMS_DRIVE_ctrWotDeratingActive	BMS_Debug_1Hz_89 7E2 8 89 00 00 7B 2A AA CB 02 = BMS_1HZDBG_CTR_WOT_COUNTER [89] = 0 [0] = 1305.0 A [2A7B] = 0 [0]				
After Upgrade 1500 Amps	Image: Description of the second s	BMS_Debug_1Hz_89 7E2 8 89 00 00 59 31 85 00 00 = BMS_1HZDBG_CTR_WOT_COUNTER [89] = 0 [0] = 1516.0 A [3159] = 0 [0]				
	+ •\v• 1	BMS_Debug_1Hz_8A 7E2 8 8A 00 00 00 DE 91 00 00				
Actual Available	□	BMS_driveLimits 202 8 EA 5D 6D 9D 9D 09 8B 2D = 240.420 V [5DEA]				
	BMS_maxBusVoltage	= 403.010 V [9D6D]				
Why Lower?	BMS_maxChargeCurrent	= 246.10 A [99D]				
-	BMS_maxDischargeCurrent	= 1492.4 A [2D8B]				



Further Research

- TMS320F2809 is supported in IDA Pro
- ARBS 7E2 and 202 define max current
- Seems possible to increase speed beyond ludicrous, it has been done by others (1000 HP RWD P85)
- Just need to find the variables and "bump them up a bit", also might need to modify DU firmware
- Would be extremely dangerous to do so
- Could end up blowing up the Drive unit or battery pack, or worse, cause a fire and injury
- Still it would be interesting to reverse engineer, hit me up if you would like to assist, I have a dug a lot deeper than the information I am presenting here
- Would like to understand shunt parameters CAU1, CGI1



Referenced Material, Acknowledgements

Spaceballs movie, inspiration for Tesla Ludicrous https://www.imdb.com/title/tt0094012/ P85D announcement https://www.tesla.com/blog/dual-motor-model-s-and-autopilot Ludicrous announcement and P85D upgrade offer https://www.tesla.com/blog/three-dog-day What is a current shunt? https://youtu.be/j4u8fl31sgQ (electroboom) TMS320 datasheet https://www.ti.com/product/TMS320F2809 Intrepid Control Systems, makers of Vehicle Spy software https://intrepidcs.com/ Bitbuster, for allowing use of lift and garage The people who helped with the Toolbox reversing, you know who you are Tesla security team for letting me do this talk